

FIG. 1




FIG. 2






FIG. 3




09698185-10200W

FIG. 4


FOURTH STEP



FIFTH STEP



SIXTH STEP




TO SEVENTH STEP


000001-5876560

FIG. 5

SEVENTH STEP



EIGHTH AND  
NINTH STEP



COMPLETE

09599195-103000

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14








FIG. 15



0959495-102000

09598195-103000

FIG. 16



000001 98189600

FIG. 17





FIG. 18



000201-58786960

FIG. 19




FIG. 20




FIG. 21





FIG. 22



0959185-102000

09509185 103000

FIG. 23




FIG. 24




FIG. 25




FIG. 26a





FIG. 26b



000007-98188960

**SECRET**

FIG. 27








FIG. 28



00508185-103000



000207-56786560

FIG. 31




FIG. 32




FIG. 33a





FIG. 33b



000207-56786960

FIG. 34a




FIG. 34b





FIG. 35



0050406 102000

FIG. 36





FIG. 37



09598195 103000

**SECRET**

**CONFIDENTIAL**







FIG. 40





FIG. 41



PHYSICAL VALUES AND SPUTTER RESISTANCE OF STRESS RELAXATION LAYER CANDIDATE MATERIAL  
(X: OCCURRENCE OF CRACKS, △: OCCURRENCE OF WRINKLE, ○: NO ABNORMALITY)